

Inspection Photos

July 26, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 430072

Location Name: Welker /34-11

Inspection Document #: 702800485

Moffat County, CO

SWSE Section 11 T6N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Welker /34-11
Location ID: 430072



Photo 1. Photo shows Location #430072 has not been built. There is no evidence of the abandoned location.

