

Inspection Photos and Issue Report

7/27/2022

Operator: CAERUS PICEANCE LLC # 10456

Location #479185

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479185



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location, construction activities “in-process”, and the pre-existing TLQ facility.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479185



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479185



Photo 3: Topsoil stockpile. Straw wattle implemented at base of pile to minimize sediment transport. Topsoil pile is currently at risk to wind erosion- continue to maintain stockpile, ensure BMPs are implemented/maintained to ensure soils remain protected.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479185



Photo 4: Wattles installed along current (construction) disturbance perimeter. Photo left also shows perimeter stormwater diversion ditch and culvert in place to divert runoff into sediment traps located on the south and west end of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479185



Photo 5: Sediment traps on south/west ends of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479185



Photo 6: Culvert on south end of the Location filling with sediment.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #479185



Photo 7: Only signage posted at the Location- Signage not associated with the ELU O13-496 Pad Location; Location signage per Rule 605.a missing. Form 2A information also not posted.

