

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403121840

Date Received:

07/29/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

Labowskie, Steve

steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500246

Inspection Date: 07/18/2022

FIR Submit Date: 07/19/2022

FIR Status:

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 334008

Location Name: ZELLITTI GU A-M34N9W Number: 33NENE County: LA PLATA

Qtrqtr: NENE Sec: 33 Twp: 34N Range: 9W Meridian: M

Latitude: 37.151392 Longitude: -107.823557

FACILITY - API Number: 05-067-00 Facility ID: 297399

Facility Name: ZELLITTI A Number: 4

Qtrqtr: NENE Sec: 33 Twp: 34N Range: 9W Meridian: M

Latitude: 37.151392 Longitude: -107.823557

CORRECTIVE ACTIONS:

1 CA# 163419

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/27/2022

Response: CA COMPLETED

Date of Completion: 07/27/2022

Operator  
Comment:

Wellhead soil cleaned up and contaminated soil inside sound wall cleaned up.

COGCC Decision:

Spare piping removed from location.

COGCC Decision: \_\_\_\_\_

--

CA completed. See attached photos.

Signed: \_\_\_\_\_

Date: 7/29/2022 2:17:06 PM

403121843	Zelliti A4, Phillips A2 & A4, CA Completion Photos
-----------	--

Page 2 of 2