

Inspection Photos
Location Name: Smith Wolter B1
Location ID: 326118



IMG 01
Well sign



IMG 02
Location overview



IMG 03
Location overview



IMG 04
Stormwater channel in access road



IMG 05
Cut slope erosion channels



IMG 06

Path of stormwater and sediment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources