

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403099039

Receive Date:

07/07/2022

Report taken by:

Steven Arauza

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: CAERUS PICEANCE LLC	Operator No: 10456	Phone Numbers Phone: (970) 285-2925 Mobile: (970) 640-6919
Address: 1001 17TH STREET #1600		
City: DENVER	State: CO Zip: 80202	
Contact Person: Blair Rollins	Email: brollins@caerusoilandgas.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 23850 Initial Form 27 Document #: 403053962

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
☐ Rule 913.g: Changes of Operator.
☐ Rule 915.b: Request to leave elevated inorganics in situ.
☐ Other:

SITE INFORMATION

No Multiple Facilities

Facility Type: PIPELINE	Facility ID: 335641	API #:	County Name: GARFIELD
Facility Name: N PARACHUTE WF01B-36A36A596		Latitude: 39.577975	Longitude: -108.108661
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: NENE	Sec: 36	Twp: 5S	Range: 96W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications GM
 Most Sensitive Adjacent Land Use Non-cropland rangeland
 Is domestic water well within 1/4 mile? Yes
 Is surface water within 1/4 mile? Yes
 Is groundwater less than 20 feet below ground surface? Yes

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☐ E&P Waste
 ☒ Other E&P Waste
 ☐ Non-E&P Waste
- ☐ Produced Water
 ☐ Workover Fluids
- ☐ Oil
 ☐ Tank Bottoms
- ☐ Condensate
 ☐ Pigging Waste
- ☐ Drilling Fluids
 ☐ Rig Wash
- ☐ Drill Cuttings
 ☐ Spent Filters
- ☐ Pit Bottoms
- ☒ Other (as described by EPA)
 No impacts associated with this project have been identified

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	To be determined	Field screening and laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

This form is being submitted to comply with COGCC Rule 911.a.(4). The form serves as initial notification to decommission on-location water transfer pipeline associated with COGCC Location ID 335641. The pipeline was subject to COGCC spill location ID 482086 but through further investigation of the incident no loss of integrity or point of release was identified. Due to the location of the pipeline Caerus plans to remove it from the ground and replace it with a section of surface pipeline.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

During pipeline removal, any liquids evacuated from the pipe will be properly contained and disposed of in compliance with Rule 905. Caerus will observe and field screen the piping trench according to the COGCC Operator Guidance for Rule 911.a.(4). Soil samples will be collected from the areas of the trench most likely to be impacted such as valve can connections, elbows, and areas where field screening and observations indicate potential impacts. Soil samples will be submitted for laboratory analysis of the full list of constituents in COGCC Table 915-1. Any impacted soil will be segregated, stockpiled on site, and the extent of impacts will be investigated through additional excavation and confirmation soil sampling. A Site Diagram illustrating the approximate pipeline and previous excavation is attached to this form.

Proposed Groundwater Sampling

- ☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 8
Number of soil samples exceeding 915-1 8
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 150

NA / ND

-- Highest concentration of TPH (mg/kg) 113
-- Highest concentration of SAR 4.56
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 0

Groundwater

Number of groundwater samples collected 1
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) 20
Number of groundwater monitoring wells installed 0
Number of groundwater samples exceeding 915-1 0

ND Highest concentration of Benzene (µg/l) _____
ND Highest concentration of Toluene (µg/l) _____
ND Highest concentration of Ethylbenzene (µg/l) _____
ND Highest concentration of Xylene (µg/l) _____
NA Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

As outlined in the attached report of work completed, background soil samples were collected in support of this project.

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No source removal is anticipated as this time as no impacts associated with the pipeline have been identified. If impacts are identified, an assessment will be made to select the most appropriate strategy for removal of the impacts.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A remediation plan will be presented to the COGCC if impacts are observed during the proposed activities.

Soil Remediation Summary

☐ In Situ

☐ Ex Situ

 Bioremediation (or enhanced bioremediation)

 Excavate and offsite disposal

_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

If Yes: Estimated Volume (Cubic Yards) _____

Name of Licensed Disposal Facility or COGCC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other Q2 2022 REM update and NFA request

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Per Rule 705.b, and in line with guidance laid out in the SBAP, Caerus has general liability insurance in the amount of \$1M, and Caerus has umbrella insurance, which sits over the general liability insurance in the amount of \$75M. The umbrella and general liability insurance covers property damage, bodily injury to third parties, and sudden or accidental pollution under a combined \$76M.

Operator anticipates the remaining cost for this project to be: \$ _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes _____

If YES:

☒ Compliant with Rule 913.h.(1).☐ Compliant with Rule 913.h.(2).☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? Yes _____

Does the previous reply indicate consideration of background concentrations? Yes _____

Does Groundwater meet Table 915-1 standards? Yes _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

All disturbance areas will be returned to grade with suitable material in preparation for final reclamation activities pursuant to COGCC 1000 Series Rules.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 05/09/2022

Proposed site investigation commencement. _____

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

As part of spill investigation activities on Spill # 482086, Caerus excavated the water dumpline to determine the point of release of the suspected spill. Excavation and inspection results determined no integrity issues with the pipeline, but after facility review by the Production Department it was determined best to remove the pipeline and replace it with a surface pipeline. Caerus collected a suspected point of release sample following the failed pressure test, and following pipeline removal collected samples from each end of the pipeline as the most likely points for failure and impacts associated with the pipeline. Based on field investigation, field screening and sample collection outlined in the attached report of work completed, Caerus requests closure and no further action of Remediation Project Number 23850, as impacts were not identified due to the suspected spill and subsequent removal of the water dumpline on the well pad.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Blair Rollins

Title: EHS Specialist

Submit Date: 07/07/2022

Email: brollins@caerusoilandgas.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Steven Arauza

Date: 08/02/2022

Remediation Project Number: 23850

Condition of Approval**COA Type****Description**

	Based on review of information presented it appears that no further action is necessary at this time, and COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if surface and/or ground water is found to be impacted, then further investigation and/or remediation activities will be required at the site. In addition, the non-working surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules including the establishment of vegetative cover on non-cropland and successful growth on cropland. Landowner must approve reclamation of cropland.
1 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403099039	FORM 27-SUPPLEMENTAL-SUBMITTED
403099058	SITE INVESTIGATION REPORT

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)