

Inspection Photos
Location Name: Becker Ranch 5MR-TB Pad
Facility ID: 481806



Photo #1 Location

Inspection Photos

Location Name: Becker Ranch 5MR-TB Pad

Facility ID: 481806



Photo #2 Stained Soil



Photo #3 Stained Soil



Inspection Photos

Location Name: Becker Ranch 5MR-TB Pad

Facility ID: 481806



Photo #4 Oily Waste on skid



Photo #5 Oily Waste on skid