

Inspection Photos
Location Name: Becker Ranch 5RU-TB Pad
Facility ID: 481807




Photo #1 Location

Inspection Photos
Location Name: Becker Ranch 5RU-TB Pad
Facility ID: 481807



Photo #2 Oily Waste

Photo #3 Oily Waste

Inspection Photos
Location Name: Becker Ranch 5RU-TB Pad
Facility ID: 481807



Photo #4 Stained Soil

Photo #5 Stained Soil

Inspection Photos
Location Name: Becker Ranch 5RU-TB Pad
Facility ID: 481807



Photo #6 Stained Soil

Photo #7 Stained Soil