

Inspection Photos
Location Name: BASHOR PC /AA17-15
Location #: 306263



Photo #1

Bashor PC AA17-15 (05-123-24323) Wellsite
Temporarily Abandoned | TA



Photo #2

Bashor PC AA17-21, 17-13, 17-15, 17-16, 17-22, 17-23,
17-24, 17-41, Peppler PC AA17-20 Battery site
Abandoned: ALL Equipment removed
Formerly served:
Bashor 17-42 ; Plugged & Abandoned | PA