

Final Reclamation Inspection

Date: 07/05/2022

Operator: WESTERN OPERATING COMPANY- 95620

Location ID: 313662

Inspection Document #: 696105288

Morgan County, CO

NENW Section 27 T1N R56W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PETERSON MAX #5
Location ID: 313662



Photo 1. Access road photo taken south of location, facing west. Access road has not been reclaimed, e.g. not recontoured or regraded.

Inspection Photos
Location Name: PETERSON MAX #5
Location ID: 313662



Photo 2. Access road photo taken south of location, facing east. Access road has not been reclaimed, e.g. not recontoured or regraded.

Inspection Photos
Location Name: PETERSON MAX #5
Location ID: 313662



Photo 3. Location photo taken from southern portion, facing north. Non-uniform vegetation cover resulting in bare soil. Debris (pipe fittings, concrete cores) left on location, highlighted in red.

Inspection Photos
Location Name: PETERSON MAX #5
Location ID: 313662



Photo 4. Location photo taken from western portion, facing east. Non-uniform vegetation cover resulting in bare soil. Debris (pipe fittings, concrete cores) left on location.

Inspection Photos
Location Name: PETERSON MAX #5
Location ID: 313662



Photo 5. Location photo taken from northern portion, facing south. Non-uniform vegetation cover resulting in bare soil. Debris (pipe fittings, concrete cores) left on location.

Inspection Photos
Location Name: PETERSON MAX #5
Location ID: 313662



Photo 6. Location photo taken from eastern portion, facing west. Non-uniform vegetation cover resulting in bare soil. Debris (pipe fittings, concrete cores) left on location.