

Interim Reclamation and Stormwater Inspection

Date:07/05/2022

Operator: WESTERN OPERATING COMPANY-95620

Location ID: 313667

Inspection Document #: 696105296

Morgan County, CO

SWSE Section 22 T1N R56W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PETERSON P F 1
Location ID: 313667



Photo 1. Access road photo taken southeast of location, facing north. Photo illustrates erosion (blue) and new two track road (red).

Inspection Photos
Location Name: PETERSON P F 1
Location ID: 313667



Photo 2. Access road photo taken east of location, facing east. Photo illustrates erosion (blue) on existing access road and new two track (red) on right side of photo.

Inspection Photos
Location Name: PETERSON P F 1
Location ID: 313667



Photo 3. Access road photo taken east of location, facing east. Erosion highlighted in blue.

Inspection Photos
Location Name: PETERSON P F 1
Location ID: 313667



Photo 4. Location photo taken west of location, facing east. Non-uniform vegetation cover resulting in bare soils.

Inspection Photos
Location Name: PETERSON P F 1
Location ID: 313667




Photo 5. Location photo taken from southeastern portion, facing northwest. Non-uniform vegetation cover resulting in bare soils.

Inspection Photos
Location Name: PETERSON P F 1
Location ID: 313667



Photo 6. Location photo taken from west portion, facing east. Unused equipment highlighted in red.