

Interim Reclamation and Stormwater Inspection

Date:07/07/2022

Operator: CRESTONE PEAK RESOURCES OPERATING
LLC-10633

Location ID: 321532

Inspection Document #: 696105298

Broomfield County, CO

NWSW Section 23 T1N R68W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Helen #14-23
Location ID: 321532



Photo 1. Noxious weeds present around location perimeter, photo facing east.

Inspection Photos
Location Name: Helen #14-23
Location ID: 321532



Photo 2. Noxious weeds present around location perimeter, photo facing west.

Inspection Photos
Location Name: Helen #14-23
Location ID: 321532



7/7/22, 11:58 AM
+40.033293,-104.977117
Broomfield, CO 80516

Photo 3. Canada Thistle outlined in red and Musk Thistle outlined in orange, photo facing west.