

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /PE-25

Location ID: 423081



Photo #7379 from entrance to location.



Photo #7380 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /PE-25

Location ID: 423081



**Photo #7381** Portable compressor being used to unload the PE25 federal 25-5A well.

**Photo #7384** portable meter house.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /PE-25

Location ID: 423081



Photo #7385 Portable compressor.



Photo #7383 Iron skid.