

Reclamation Inspection

July 20, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 287848

Inspection Document #: 697504075

Weld County, CO

NWNW Section 18 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 1. Photo taken from the entrance of the location. Photo illustrates the Operator sign which needs to be updated- the emergency phone number is not accurate and the title needs to be updated to state that NO E&P Waste is accepted.



Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 2. Photo taken from the northern location, facing Southwest. Photo illustrates one of the gravel (clean roadbase) stockpiles that is from interim and final reclamation locations being reused.



Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 3. Photo taken from the north location, facing West. Photo illustrates an unknown spill.



Photo 4. Photo taken from the previous photo. Photo illustrates trash within the spill area. Trash and debris were observed throughout other areas of the location.

Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 5. Photo taken from the western location, facing South. Photo illustrates stormwater retention ponds. Operator will need to perform sampling beneath the liner.



Inspection Photos

Location Name: CENTRALIZED LAND TREATMENT FACILITY

Location ID: 287848



Photo 6. Photo taken from the western location, facing East. Photo illustrates the vegetated area that appears to be recently mowed, likely for performing weed control.

