

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4SENW

Location ID: 334697



Photo #7416 from entrance to location.



Photo #7417 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /4SENW

Location ID: 334697



Photo #7418 Vent pipes on tank open ended.