

# Inspection Photos

August 1, 2022

Operator: Beeman Oil & Gas Inc- #7125

Location ID: 316741

Location Name: GRASSY CREEK COAL CO-66N87W /35NENE

Inspection Document #: 702800546

Routt County, CO

NENE Section 35 T6N R87W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: GRASSY CREEK COAL CO-66N87W /35NENE

Location ID: 316741



**Photo 1.** Photo taken from the northwest shows an overview of the Location.



**Photo 2.** Photo taken at the south of the Location shows the wellhead.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800546



Inspection Photos  
Location Name: GRASSY CREEK COAL CO-  
66N87W /35NENE  
Location ID: 316741



**Photo 3.** Photo taken from the southwest of the Location shows stained soils beneath the pump jack exhaust.



**Photo 4.** Refer to Photo 3 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800546



Inspection Photos  
Location Name: GRASSY CREEK COAL CO-  
66N87W /35NENE  
Location ID: 316741



**Photo 5.** Photo taken from the east of the Location shows areas not used for production operations are colonized by perennial grasses.



**Photo 6.** Refer to Photo 5 comment.