

Inspection Photos

August 1, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 437712

Location Name: NORTH HAYDEN /1-26

Inspection Document #: 702800548

Routt County, CO

SENE Section 26 T7N R88W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 1. Photo taken from the northwest of the Location on the access road (road area indicated by red lines) shows the road is completely colonized by Kochia, an annual undesirable plant species/weed.



Photo 2. Photo taken from the northwest of the Location shows a close up of the vegetation on the access road. It is entirely colonized by Kochia, an annual undesirable plant species/weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800548

Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 3. Photo shows the access road.



Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 4. Photo taken from the north at the Location entrance shows an overview of the reclaimed Location.



Photo 5. Photo taken from the north of the Location shows areas of bare ground at the northwest where vegetation establishment is not uniform.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800548

Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 6. Photo shows a patch of Canada thistle, a CO List B Noxious Weed. Noxious weeds were scattered throughout the Location.



Photo 7. Photo shows musk thistle, a CO List B Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800548

Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 8. Photo shows a patch of whitetop, a CO List B Noxious Weed.



Photo 9. Photo shows a patch of cheatgrass, a CO List C Noxious Weed and Canada thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800548

Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 10. Photo shows rill erosion occurring on bare soil at the south of the Location.




Photo 11. Photo taken from the center of the Location shows rill erosion (red arrows). Cheatgrass and Canada thistle are also present in the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800548

Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 12. Photo shows rill erosion occurring on bare soil at the south of the Location.



Inspection Photos
Location Name: NORTH HAYDEN /1-26
Location ID: 437712



Photo 13. Photo taken from the northwest of the Location shows the reference area plant community.



Photo 14. Photo shows a close up of the reference area plant community.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800548