

Final Reclamation Inspection

Date: 08/03/2022

Operator: Noble Energy INC-100322

Location ID: 319754

Inspection Document #: 696105335

Adams County, CO

NENE Section 14 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HECKENDORF #1
Location ID: 319754



Photo 1. Location photo taken from the southern portion, facing north. Location (outlined in red) revegetation is not reflective of adjacent perennial crop, alfalfa.

Inspection Photos
Location Name: HECKENDORF #1
Location ID: 319754



Photo 2. Location photo taken from center of location, facing north. See comments in Photo 1.

Inspection Photos
Location Name: HECKENDORF #1
Location ID: 319754



Photo 3. Location photo taken from center of location, facing northwest. See comments in Photo 1.

Inspection Photos
Location Name: HECKENDORF #1
Location ID: 319754



Photo 4. Location photo taken from center of location, facing south. See comments in Photo 1.

Inspection Photos
Location Name: HECKENDORF #1
Location ID: 319754



Photo 5. Location photo taken from northwestern portion, facing southeast. See comments in Photo 1.