

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Spill/Release ID: 475580
Inspection Date: July 12, 2022

**Potentially impacted material
around a pump near the UIC well.**

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Potentially impacted material
around a pump near the UIC well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Potentially impacted fluids within the secondary containment structure for the pump near the UIC well.




Jul 12, 2022 1:46:21
+40.0828N -108.610



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Spill/Release ID: 475580
Inspection Date: July 12, 2022


Potentially impacted material
around the UIC well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Spill/Release ID: 475580
Inspection Date: July 12, 2022

Potentially impacted material
around the UIC well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Potentially impacted material and uncapped flowlines exiting the pump house adjacent to the tank battery secondary containment structure.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Potentially impacted material and uncapped flowlines exiting the pump house adjacent to the tank battery secondary containment structure.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

A section of the tank battery secondary containment structure has been removed to accommodate a flowline near the adjacent pump building (red area). Note the various sized patches on the tank battery secondary containment structure.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

West steel AST, tank appears to be unused and has an open man hatch. Note the potential impacts around the man hatch.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

**Tank battery secondary
containment structure liner
patches in disrepair.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Various sized holes in the tank
battery secondary containment
structure.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Spill/Release ID: 475580
Inspection Date: July 12, 2022

**Various sized holes in the tank
battery secondary containment
structure.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: FLETCHER GULCH 3-31
Location ID: 311853
Spill/Release ID: 475580
Inspection Date: July 12, 2022

Overview of the tank battery.



Jul 12, 2022 1:49:12
+40.0832N -108.609



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Unused equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Unused equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: FLETCHER GULCH 3-31

Location ID: 311853

Spill/Release ID: 475580

Inspection Date: July 12, 2022

Unused equipment.



Jul 12, 2022 1:54:17
+40.0832N -108.610



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources