

Inspection Photos

August 08, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 311604

Location Name: GL-67S93W /18SWSE

Inspection Document #: 702800555

Garfield County, CO

SWSE Section 18 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GL-67S93W /18SWSE
Location ID: 311604



Photo 1. Photos taken from the Location entrance at the west show an overview of the production area. Photos show pad surface has been regraded and gravel applied.



Inspection Photos
Location Name: GL-67S93W /18SWSE
Location ID: 311604



Photo 2. Photo taken from the south in the interim area shows plumeless thistle and houndstongue (CO List B Noxious Weeds).



Photo 3. Photo taken from the south of the Location shows scentless chamomile (CO List B Noxious Weed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800555

Inspection Photos
Location Name: GL-67S93W /18SWSE
Location ID: 311604



Photo 4. Photo taken from the south of the Location in the interim area shows the fence around the rock feature is in disrepair. Red circles indicate houndstongue and scentless chamomile.

