

Inspection Photos and Issue Report

8/10/2022

Operator: CAERUS PICEANCE LLC # 10456

Location #312380

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #312380



August 10, 2022



August 10, 2022

Photo 1: Photos taken from the east end of the Location, facing northeast, east. Photos examples showing Final reclamation (including removal of gravel, compaction alleviation, recontouring/regrading, and revegetating) has not been performed on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #312380



Photo 2: Photos show cut and fill slopes of the Location; location has not been recontoured/regraded.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #312380



Photo 3: Photos taken from the Location. Photos examples showing gravel has not been removed, and Undesirable Plant establishment throughout the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #312380



Photo 4: Photo example showing the O&G access road leading the Location has not been reclaimed.