

Inspection Photos and Issue Report

8/10/2022

Operator: CAERUS PICEANCE LLC # 10456

Location #312686

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location #312686



Photo 1: Photos show southern areas of the Location that have not been reclaimed in accordance with 1004 Rules; gravel has not been removed, and areas have not been decompacted, recontoured/regraded and revegetated.