

# Inspection Photos

August 8, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 414294

Location Name: Beaver Creek Ranch 08-13 Pad

Inspection Document #: 702800566

Garfield County, CO

SWSW Section 8 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Beaver Creek Ranch 08-13 Pad  
Location ID: 414294



8/8/22  
+39.455044,-107.805979  
147° SE

**Photo 1.** Photo shows an overview of the production area. Photo also shows gravel has been added to the pad surface to the west.



8/8/22  
+39.455044,-107.805979  
143° SE

**Photo 2.** Photo shows an overview of the production area. Photo also shows gravel has been added to the pad surface to the west.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800566

## Inspection Photos

Location Name: Beaver Creek Ranch 08-13 Pad

Location ID: 414294



**Photo 3.** Photo shows an overview of the production area. Photo also shows gravel has been added to the pad surface to the west.



**Photo 4.** Photo shows control measures to protect and stabilize the production areas remain missing or insufficient at the east of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800566

Inspection Photos

Location Name: Beaver Creek Ranch 08-13 Pad

Location ID: 414294



**Photo 5.** Photo shows control measures to protect and stabilize the production areas remain missing or insufficient at the east of the Location.



**Photo 6.** Photo shows control measures to protect and stabilize the production areas remain missing or insufficient at the east of the Location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800566

Inspection Photos

Location Name: Beaver Creek Ranch 08-13 Pad

Location ID: 414294



**Photo 7.** Photo taken from the southern interim area of the Location shows Russian olive, a CO List B Noxious Weed.



**Photo 8.** Photo taken from the north of the Location shows an example of plumeless thistle, a CO List B Noxious Weed found throughout the Location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800566

Inspection Photos  
Location Name: Beaver Creek Ranch 08-13 Pad  
Location ID: 414294



**Photo 9.** Photo taken from the south shows the original cut slope still present on Location.

