

Inspection Photos

API: 061-06861

Operator: OKT RESOURCES LLC

Inspection Date: 8/10/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06861 - Date: 8/10/2022

Inspection Photos



Photo 1. Facing north toward the location. The location consists of undesirable weed and sparse vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06861 - Date: 8/10/2022

Inspection Photos



Photo 2. Facing south at the location. The location consists of undesirable weed and sparse desirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06861 - Date: 8/10/2022

Inspection Photos



Photo 3. Facing west at the location. The location consists of undesirable weed and sparse desirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06861 - Date: 8/10/2022

Inspection Photos



Photo 4. Facing north toward the undisturbed reference area . The reference area consists of native vegetation including Blue grama, Buffalo grass, Sand dropseed, Sand sage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06861 - Date: 8/10/2022