

Inspection Photos
Location Name: Susie 11-9
Location ID: 318999



Location Sign at County Road 89



Former production facilities looking northeast

Inspection Photos
Location Name: Susie 11-9
Location ID: 318999



Former production facilities looking northeast



Monitoring well installed at location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Susie 11-9
Location ID: 318999



Monitoring wells immediately north of location



Former production facilities looking west



Inspection Photos
Location Name: Susie 11-9
Location ID: 318999



Former produced water pits, looking north



Former produced water pits looking south



Inspection Photos
Location Name: Susie 11-9
Location ID: 318999



Susie 11-9 well location

