

Inspection Photos and Issue Report

8/15/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334776

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334776



August 15, 2022

Photo 1: Photos 1-4 taken from the production areas of the Location. Photos show stormwater and erosion controls to stabilize the location, and minimize degradation, tracking and offsite sediment transport are missing or insufficient.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334776



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334776



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334776



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334776



August 15, 2022



August 15, 2022

Photo 5: Photo taken from interim areas of the Location. Photos examples showing noxious weeds (plumeless thistle, musk thistle – Purple headed flowers, white fluffy seeds) observed established on the upslope and downslope areas of the Location.