

Inspection Photos

API: 071-09478

Operator: OGRIS OPERATING LLC

Inspection Date: 8/19/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09478 | Date: 8/19/2022

Inspection Photos



Photo 1. Facing south toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09478 | Date: 8/19/2022

Inspection Photos



Photo 2. There is a dripping water leak at the wellhead that needs to be repaired. The tank shown in the photo appears to be unused and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09478 | Date: 8/19/2022

Inspection Photos



Photo 3. There is a dripping water leak at the wellhead that needs to be repaired. The tank shown in the photo appears to be unused and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09478 | Date: 8/19/2022