

Inspection Photos
Location Name: Zarlengo 24-4
Location ID: 320458



Photo 1 Stained soil around well head. Unused equipment (pipe and fencing). Weeds around equipment



Photo 2 Weeds around equipment, unused equipment (belt guards pipe and fencing)

Inspection Photos
Location Name: Zarlengo 24-4
Location ID: 320458



Photo 3 stained soil around PU motor



Photo 4 Weeds around equipment

Inspection Photos
Location Name: Zarlengo 24-4
Location ID: 320458



Photo 5 Weeds on location



Photo 6 TNK BTRY. Weeds inside BMP.

Inspection Photos
Location Name: Zarlengo 24-4
Location ID: 320458



Photo 7 Bird netting in disrepair



Photo 8 stained soil around Produced water tank.

Inspection Photos
Location Name: Zarlengo 24-4
Location ID: 320458



Photo 9 Stained soil around crude oil loadout line