

Final Reclamation Inspection

Date: 08/17/2022

Operator: GREAT WESTERN OPERATING COMPANY LLC-10110

Location ID: 320352

Inspection Document #: 696105364

Adams County, CO

NESE Section 7 T1S R67W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 1. Location photo taken from southern portion, facing northwest. Photo illustrates gravel/road base observed on location; some desirable vegetation growth present.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 2. Location photo taken from southern portion, facing northwest. See comments in Photo 1.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 3. Location photo taken from southern portion, facing north. Photo illustrates some desirable perennial vegetation observed; annual weedy vegetation also observed (Russian thistle and Kochia) on reclamation area.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 4. Location photo taken from center portion, facing east. Annual weedy vegetation observed on location (Russian Thistle highlighted in red).

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 5. Location photo taken from center portion, facing southwest. Photo illustrates annual weedy vegetation, mainly Kochia and Russian Thistle. Some desirable perennial vegetation observed, e.g. Western Wheat.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 6. Location photo taken from center portion, facing north. See comments in Photo 5.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 7. Location photo taken from northern portion, facing northwest. See comments in Photo 5.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 8. Location photo taken from northern portion, facing southeast. See comments in Photo 5.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 9. Location photo taken near old well location, facing north. Photo illustrates presence of annual weedy vegetation, Kochia.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 10. Reference area photo taken west of location, facing northwest.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 11. Access road photo taken south of location, facing southeast. Photo illustrates access road has not been reclaimed with presence of gravel/road base.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 12. Access road photo taken south of location, facing northwest. See comments in Photo 11.

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 13. Access road photo taken south of location, facing southeast. Photo illustrates some desirable vegetation along portions of the access road; gravel/road base observed within new growth (highlighted in red).

Inspection Photos
Location Name: WIERMAN 43-7 (1)
Location ID: 320352



Photo 14. Reference area photo taken east of access road, facing east.