

Final Reclamation Inspection

Date: 08/17/2022

Operator: BATES* JAMES EDWARD- 6575

Location ID: 319816

Inspection Document #: 696105365

Adams County, CO

NWSE Section 7 T1S R67W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 1. Location photo taken from southeastern portion, facing northwest. Photo illustrates location has not been reclaimed with presence of annual weedy vegetation; mainly kochia and russian thistle.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 2. Location photo taken from southeastern portion, facing west. See comments in Photo 1.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 3. Location photo taken from southern portion, facing northwest. Photo illustrates presence of annual weedy vegetation, mainly russian thistle, and non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 4. Location photo taken from southern portion, facing northeast. See comments in Photo 3.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 5. Location photo taken from center portion, facing northwest. See comments in Photo 3.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 6. Location photo taken from center/northern portion, facing north. Photo illustrates bare soil and presence of rock and gravel within reclamation area.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 7. Location photo taken from center portion, facing southwest. See comments in Photo 6.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 8. Location photo taken from center portion, facing south. Photo illustrates presence of annual weedy vegetation, mainly russian thistle.

Inspection Photos
Location Name: WIERMAN #2
Location ID: 319816



Photo 9. Location photo taken from southern portion, facing south. Photo illustrates location has bare soil resulting from non-uniform vegetation cover and presence of rock and gravel.