

Final Reclamation Inspection

May 24th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323090

Inspection Document #: 701900390

NWSE Section 20 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 1. 2021 aerial imagery of the well pad and associated tank battery.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 2. Overview photo of the well pad taken at ground level from the northern edge looking south.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with reference area (see photo 5).

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 5. Reference area.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 6. Overview photo of the tank battery taken at ground level from the western edge looking east.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 7. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 8. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Peschel 43-20
Location ID: 323090



Photo 9. Tank battery reference area.