

Inspection Photos

API: 071-07711

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/23/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 1. Facing southeast at the beginning of the access road. The water bars installed along the road need maintenance. Stormwater is being directed back onto the road shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 2. Facing southeast along the access road. There is erosion occurring along the road due to issue shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 3. Facing southeast further along the access road. The water bars installed along the road need maintenance. Stormwater is being directed back onto the road shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 4. Facing southeast at the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 5. Facing east toward the location. Desirable vegetation is progressing well throughout most areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 6. This area at the east side of the location approximately 50'x50' which has not established desirable vegetation . This area should be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 7. Facing west along the fill slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022

Inspection Photos



Photo 8. Facing northeast toward the surrounding undisturbed reference area vegetation cover which consists of Blue grama, Sand dropseed, Prairie threeawn, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 8/23/2022