

Inspection Photos

August 23, 2022

Operator: White River Development Company LLC - #10271

Location ID: 324132

Location Name: Woodward-64S94W /22SESW

Inspection Document #: 702800570

Garfield County, CO

SESW Section 22 T4S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Woodward-64S94W /22SESW

Location ID: 324132



Photo 1. Photo taken from the northwest shows an overview of the Location. Approximate areas of failed reclamation are indicated by red circles. Refer also to Photos 3-6.



Photo 2. Photo taken from the southeast at the Location entrance shows the unreclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800570

Inspection Photos

Location Name: Woodward-64S94W /22SESW

Location ID: 324132



Photo 3. Photo taken from the center of the Location shows the general area around the former site of the wellhead. The plant covering much of the ground surface is prostrate knotweed, an annual, introduced, undesirable species. The taller plants throughout the photo are noxious weeds.



Photo 4. Photo shows a close-up of the ground surface of the area shown in Photo 3.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800570

Inspection Photos

Location Name: Woodward-64S94W /22SESW

Location ID: 324132



8/23/22
+39.682241,-107.930763
114° SE

Photo 5. Photo taken from the south of the Location shows where revegetation has failed. Areas of failed revegetation in photo include the general area around the Location entrance and the former site of the tank battery and other equipment. Photo also shows the area is dominated by noxious weeds.



8/23/22
+39.681721,-107.930664
340° N

Photo 6. Photo taken from the south of the Location shows where revegetation has failed at the former site of the tank battery and other equipment. Photo also shows the area is dominated by noxious weeds.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800570

Inspection Photos
Location Name: Woodward-64S94W /22SESW
Location ID: 324132



Photo 7. Photo taken from the center of the Location shows the start of the disturbed area vegetation monitoring transect. The taller plants throughout the photo are noxious weeds.



Photo 8. Photo taken from the center of the Location shows the ground surface at the start of the disturbed area vegetation monitoring transect.



Inspection Photos
Location Name: Woodward-64S94W /22SESW
Location ID: 324132



Photo 9. Photo taken from the center of the Location shows the end of the disturbed area vegetation monitoring transect. The taller plants throughout the photo are noxious weeds.



Photo 10. Photo taken from the center of the Location shows the ground surface at the end of the disturbed area vegetation monitoring transect. Red circles indicates musk thistle, a noxious weed.



Inspection Photos
Location Name: Woodward-64S94W /22SESW
Location ID: 324132



Photo 11. Photo taken to the west of the Location shows the start of the reference area vegetation monitoring transect.



Photo 12. Photo taken to the west of the Location shows the ground surface at the start of the reference area vegetation monitoring transect.



Inspection Photos

Location Name: Woodward-64S94W /22SESW

Location ID: 324132



Photo 13. Photo taken to the west of the Location shows the end of the reference area vegetation monitoring transect.



Photo 14. Photo taken to the west of the Location shows the ground surface at the end of the reference area vegetation monitoring transect.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800570