

Inspection Photos

August 23, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334282

Location Name: GMU-66S93W /35NWSW

Inspection Document #: 702800571

Garfield County, CO

NWSW Section 35 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GMU-66S93W /35NWSW
Location ID: 334282



Photo 1. Photo taken from the southeast of the Location shows a pig launcher/receiver and associated road remaining on Location.



Photo 2. Photo taken from the southeast of the Location shows a pig launcher/receiver remaining on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800571

Inspection Photos
Location Name: GMU-66S93W /35NWSW
Location ID: 334282



Photo 3. Photo taken from the northeast of the Location shows Russian knapweed, a CO List B Noxious Weed.



Inspection Photos
Location Name: GMU-66S93W /35NWSW
Location ID: 334282



Photo 4. Photo taken from the north shows an overview of the lower/eastern portion of the reclaimed Location. The area is dominated by perennial grasses. A residential road/driveway bisects the Location.



Photo 5. Photo taken from the north shows an overview of the upper/western portion of the reclaimed Location at the former site of the wellheads. The area is dominated by perennial grasses.

Inspection Photos
Location Name: GMU-66S93W /35NWSW
Location ID: 334282



Photo 6. Photo taken from the east shows the lower/southeastern portion of the reclaimed Location at the former site of the tank battery. The area is dominated by perennial grasses. Note the straw wattle, which must be removed for the site to receive a passing final reclamation inspection.



Inspection Photos
Location Name: GMU-66S93W /35NWSW
Location ID: 334282



Photo 7. Photo taken from the center of the Location shows the start of the disturbed area vegetation monitoring transect.



Photo 8. Photo taken to the south of the Location shows the start of the reference area vegetation monitoring transect.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800571