


Inspection Photos
Location Name: HSR-Nies 15-15
Location ID: 330259



Colorado Oil & Gas Conservation Commission
40.39391, -104.87626, 1494.3m, 345°
Aug 24, 2022 9:31:41 AM

Photo 1: Wellhead Sign



Colorado Oil & Gas Conservation Commission
40.39394, -104.87624, 1502.0m, 140°
Aug 24, 2022 9:31:51 AM

Photo 2: Wellhead

Inspection Photos
Location Name: HSR-Nies 15-15
Location ID: 330259



Photo 3: Centralized Tank Battery; weeds



Photo 4: Equipment

Inspection Photos
Location Name: HSR-Nies 15-15
Location ID: 330259



Photo 5: Debris



Photo 6: Debris

Inspection Photos
Location Name: HSR-Nies 15-15
Location ID: 330259



Photo 7: Weeds