

# Inspection Photos and Issue Report

8/25/2022

Operator: D & G ROUSTABOUT SERVICE -  
22370CORP - 10539  
Location #322318  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370CORP - 10539

Location #322318



August 25, 2022



August 25, 2022

**Photo 1:** Photos provide overview of the Location. Vegetation observed on the working pad is predominantly undesirable and noxious plant species.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370CORP - 10539

Location #322318



**Photo 2:** Photo shows weeds have re-established at and around production equipment on the Location; this is a fire hazard



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370CORP - 10539

Location #322318



**Photo 3:** Photo shows weeds have re-established at and around production equipment on the Location; this is a fire hazard





## Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370CORP - 10539

Location #322318



**Photo 3:** Photo shows produced water tank, and earthen berm (secondary containment). Photo shows integrity of the BMP has not been maintained; vegetation has re-established around the production equipment, and on/within the containment BMP- BMP is compromised.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370CORP - 10539

Location #322318



**Photo 5:** Photo shows produced water tank, and earthen berm (secondary containment). Photo shows integrity of the BMP has not been maintained; vegetation has re-established around the production equipment, and on/within the containment BMP- BMP is compromised.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370CORP - 10539

Location #322318



**Photo 6:** Photo shows weeds have re-established at and around production equipment on the Location; this is a fire hazard



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources