

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403131079

Date Received:

08/09/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10409

Name of Operator: PEAKVIEW OPERATING COMPANY LLC

Address: 2427 WEST KETTLE CIRCLE

City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Walters, Steve

720-402-3081

swalters@peakviewenergy.com

Wise, Wayne

(405) 826-7013

wwise@peakviewenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700704393

Inspection Date: 07/12/2022

FIR Submit Date: 07/15/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC

Company Number: 10409

Address: 2427 WEST KETTLE CIRCLE

City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 316759

Location Name: GRASSY CREEK COAL CO-66N87W Number: 26SWNW County: ROUTT

Qtrqtr: SWN Sec: 26 Twp: 6N Range: 87W Meridian: 6  
W

Latitude: 40.449694 Longitude: -107.121523

FACILITY - API Number: 05-107- -00 Facility ID: 232664

Facility Name: GRASSY CREEK COAL CO Number: 3

Qtrqtr: SWN Sec: 26 Twp: 6N Range: 87W Meridian: 6  
W

Latitude: 40.449694 Longitude: -107.121523

CORRECTIVE ACTIONS:

1 ☒ CA# 163377

Corrective Action: Remove stained material

Date: 08/05/2022

Response: CA COMPLETED

Date of Completion: 08/04/2022

Operator Comment: Stained gravel around the engine muffler was removed and the wooden pallets stacked against the engine house were also removed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 163378

Corrective Action: Provide proper labeling

Date: 08/05/2022

Response: CA COMPLETED

Date of Completion: 08/04/2022

Operator  
Comment: Safety decals were placed on both sides of the propane tank. The safety decals warn of the tanks contents and potential fire hazards.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: \_\_\_\_\_

Title: Operations Engineer

Date: 8/9/2022 6:53:10 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403131079	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files