



Inspection Photos
107-06138
Inspection Date: 8/24/2022
All Photos taken by Kris Neidel

Photo #1 Wolf Mtn pad. All production equipment was removed and well was plugged and backfilled.



Inspection Photos
107-06138
Inspection Date: 8/24/2022
All Photos taken by Kris Neidel

Photo #2 Sample being collected at wellhead. Wood from cellar was observed in excavation. Sample was collected at approximately 7 feet below surface directly adjacent to capped wellbore.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
107-06138
Inspection Date: 8/24/2022
All Photos taken by Kris Neidel

Photo #3 photos of tank battery. 3 pot holes were dug at tank battery and observed for any detections of hydrocarbon, none were found. A sample was collected.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
107-06138
Inspection Date: 8/24/2022
All Photos taken by Kris Neidel

Photo #4 water impoundment directly adjacent to well pad. Impoundment was sampled for table 915-1.





Inspection Photos
107-06138
Inspection Date: 8/24/2022
All Photos taken by Kris Neidel

Photo #5 puddle near wellhead, no obvious signs of hydrocarbon.



Inspection Photos
107-06138

Inspection Date: 8/24/2022
All Photos taken by Kris Neidel

Photo #1 Sign at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources