

Final Reclamation Inspection

August 17, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328592

Inspection Document #: 697504148

Weld County, CO

NESW Section 34 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WOOLLEY #34-11M
Location ID: 328592



Photo 1. Photo taken north of the well location, facing South. Photo illustrates the associated tank battery is still in use by another Operator, KPK; therefore, this is a well release on an active location.

Inspection Photos
Location Name: WOOLLEY #34-11M
Location ID: 328592



Photo 2. Photo taken of the active KPK well location that is associated with the tank battery in the previous photo.

Inspection Photos
Location Name: WOOLLEY #34-11M
Location ID: 328592




Photo 3. COGCC GISOnline aerial imagery from 2017 illustrates this well in relation to the tank battery. Note- the active KPK well to the east (yellow circle).

