

This is a picture of the well sign.





Replaced the packing and cleaned up the impacted soil.

