

Final Reclamation Inspection

August 17, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 318193

Inspection Document #: 697504152

Weld County, CO

NENE Section 33 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: DUANE E. NELSON 41-33 (2-68) #1-X

Location ID: 318193



Photo 1. Photo taken from the northern location, facing South. Photo illustrates desirable vegetation is evident but will remain in process.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504152

Inspection Photos

Location Name: DUANE E. NELSON 41-33 (2-68) #1-X

Location ID: 318193



Photo 2. Photo taken along the eastern location, facing South. Photo illustrates a bare area lacking desirable establishment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504152

Inspection Photos

Location Name: DUANE E. NELSON 41-33 (2-68) #1-X

Location ID: 318193



Photo 3. Photo taken along the eastern location, facing East. Photo illustrates not all equipment has been removed.

Inspection Photos

Location Name: DUANE E. NELSON 41-33 (2-68) #1-X

Location ID: 318193



Photo 4. Photo taken along the southern location, facing South. See comments under Photo 2.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504152

Inspection Photos

Location Name: DUANE E. NELSON 41-33 (2-68) #1-X

Location ID: 318193



Photo 5. Photo taken along the central location, facing North. See comments under Photo 1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504152