

Inspection Photos and Issue Report

8/30/2022

Operator: CAERUS PICEANCE LLC

Location #448472

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #448472



Photo 1: Photos taken from the interim areas on the east end of the Location. Photos 1-2 provide an overview of the Location from south, southwest, northwest to north.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #448472



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #448472



Photo 3: Photo example showing vegetation on the interim areas; areas appear to be progressing towards COGCC uniform revegetative standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #448472



Photo 4: Photo taken from the sediment trap on the southwest end of the Location; photo shows erosion degradation observed on the south facing slopes.

Inspection Photos
Operator Name: CAERUS PIC
Location #448472



Photo 5: Photos taken from the sediment trap on the southwest end of the Location. Photo shows gulley erosion at inlet of the trap.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #448472



Photo 6: Photos taken from the access road. Photos examples showing erosion degradation evident at the stormwater diversion ditch; additional unconsolidated soils also appear to have been put into the ditch; this will contribute to sediment-laden stormwater discharge.