

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 1 – Tank Battery Signs

Photo 2 – ECDs

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 3 – VRUs



Photo 4 – Tank Battery

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 5 – LACTs



Photo 6 – East Wellheads

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Colorado Oil and Gas Conservation Commission
40.77849, -103.86123, 4655.9ft, 239°
08/31/2022 12:00:07



Colorado Oil and Gas Conservation Commission
40.77846, -103.8618, 4652.0ft, 251°
08/31/2022 12:00:51

Photo 7 – Wellhead Sign

Photo 8 – West Wellheads

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Colorado Oil and Gas Conservation Commission
40.77846, -103.86179, 4652.1ft, 239°
08/31/2022 12:00:56



Colorado Oil and Gas Conservation Commission
40.7782, -103.86163, 4645.8ft, 194°
08/31/2022 12:01:16

Photo 9 – Wellhead Sign

Photo 10 – Gas Lift Injection Meter Houses

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 11 – Tank Battery



Photo 12 – VRTs

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 13 – Labels missing or Remove if NOT IN USE



Photo 14 – Unmarked Riser

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 15 – Markings had faded no longer visible or missing



Photo 16 – Water Tank Battery

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 17 – Water Tank Battery



Photo 18 – Sand Traps and Headers

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 19 – Production Equipment



Photo 20 – Heater Treater

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 21 – Sand Traps and Headers



Photo 22 – Methanol Day Tank

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 23 – Maintenance Tank



Photo 24 – Production Equipment

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 25 – Production Equipment



Photo 26 – Compressor

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 27 – Compressor



Photo 28 – Production Equipment

Inspection Photos
Location Name: Rohn State LD03-65-1HN PAD
Location ID: 433076



Photo 29 –Weeds in Interim Reclamation Area