

Inspection Photos  
Location Name: Blehm Pad  
Location ID: 478497



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos  
Location Name: Blehm Pad  
Location ID: 478497



Colorado Oil & Gas Conservation Commission  
40.59469, -104.89123, 1535.3m, 327°  
Aug 31, 2022 10:34:58 AM

Photo 3: Wellhead Sign



Colorado Oil & Gas Conservation Commission  
40.59469, -104.89123, 1535.5m, 13°  
Aug 31, 2022 10:35:12 AM

Photo 4: Stained soil

**Inspection Photos**  
**Location Name: Blehm Pad**  
**Location ID: 478497**



**Photo 5: Stained soil**



**Photo 6: Stained soil**

Inspection Photos  
Location Name: Blehm Pad  
Location ID: 478497



Photo 7: Wellhead Sign



Photo 8: Stained soil

Inspection Photos  
Location Name: Blehm Pad  
Location ID: 478497



Photo 9: Wellhead Sign



Photo 10: Stained soil

Inspection Photos  
Location Name: Blehm Pad  
Location ID: 478497




Photo 11: Wellhead Sign



Photo 12: Stained soil

Inspection Photos  
Location Name: Blehm Pad  
Location ID: 478497



Colorado Oil & Gas Conservation Commission  
40.59467, -104.8912, 1534.3m, 307°  
Aug 31, 2022 10:36:06 AM

Photo 13: Stained soil



Colorado Oil & Gas Conservation Commission  
40.59448, -104.89121, 1532.0m, 17°  
Aug 31, 2022 10:38:09 AM

Photo 14: Wellhead Sign

Inspection Photos  
Location Name: Blehm Pad  
Location ID: 478497



Photo 15: Stained soil



Photo 16: Stained soil