

Inspection Photos and Issue Report

8/30/2022

Operator: CAERUS PICEANCE LLC

Location #445862

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #445862



August 30, 2022



August 30, 2022

Photo 1: Photos taken from the north end of the Location. Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #445862



August 30, 2022



August 30, 2022

Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #445862



Photo 3: Photo example showing vegetation on the interim areas; areas appear to be progressing towards COGCC uniform revegetative standards.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #445862



Photo 4: Photo taken from the inlet of the sediment trap on the north end of the Location. erosion degradation evident at sediment trap on the north end of the Location; inlet does not appear to have been constructed with a geotextile lining in conjunction with rip-rap armoring per good engineering practices, resulting in erosion degradation beneath the rock material; degradation also observed below the armored section of the inlet leading into the sediment trap.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #445862



Photo 5: Photo taken from the inlet of the sediment trap on the north end of the Location; erosion degradation evident at sediment trap; inlet does not appear to have been constructed with a geotextile lining in conjunction with rip-rap armoring per good engineering practices, resulting in erosion degradation beneath the rock material; degradation also observed below the armored section of the inlet leading into the sediment trap.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #445862



Photo 6: Photo taken from the sediment trap on the north end of the Location. Photo shows degradation observed below the armored section of the inlet leading into the sediment trap.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC
Location #445862



Photo 7: Photo shows sediment trap on north end of the Location. BMP does not appear to have been constructed with an engineered outlet. BMP filling with sediment- maintenance advised.