

Caerus Piceance LLC  
J6SEB  
Location # 432265



Location



location

Caerus Piceance LLC  
J6SEB  
Location # 432265



Location



location

Caerus Piceance LLC  
J6SEB  
Location # 432265



Valves missing plugs



Debris

Caerus Piceance LLC  
J6SEB  
Location # 432265



**Valves missing plugs**



**Cut slope erosion**