

Inspection Photos

August 29, 2022

Operator: EOG Resources Inc - #27742

Location ID: 313136

Location Name: Fort Reynolds State-612N92W /36SWSW

Inspection Document #: 702800642

Moffat County, CO

SWSW Section 36 T12N R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bakers Peak-611N91W /12NWSE
Location ID: 313136



Photo 1. Photo taken to the north of the Location shows the access road remains. Vegetation growth is absent in tire tracks where soils are compacted and bare.



Photo 2. Photo taken to the north of the Location shows reference area vegetation adjacent to the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800642

Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313136



Photo 3. Photo taken from the south of the Location shows gully erosion.



Photo 4. Photo taken from the center of the Location shows the vegetation community consists of native perennial grasses and occasional forbs and shrubs.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800642

Inspection Photos

Location Name: Bakers Peak-611N91W /12NWSE

Location ID: 313136



Photo 5. Photo taken from the north shows an overview of the Location.



Photo 6. Photo taken from the south shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800642

Inspection Photos
Location Name: Bakers Peak-611N91W /12NWSE
Location ID: 313136



Photo 7. Photo shows reference area vegetation to the southwest of the Location.

