

Inspection Photos

August 31, 2022

Operator: Crowheart Energy LLC - #10776

Location ID: 313092

Location Name: Blue Sky-69N91W /1SESE

Inspection Document #: 702800649

Moffat County, CO

SESE Section 1 T9N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Blue Sky-69N91W /1SESE
Location ID: 313092



Photo 1. Photo taken from the Location entrance shows an overview of the Location.



Photo 2. Photo taken from the Location entrance shows an overview of the Location.

Inspection Photos
Location Name: Blue Sky-69N91W /1SESE
Location ID: 313092



Photo 3. Photo shows the wellhead sign which does not comply with Rule 605.d.



Photo 4. Photo shows the tank battery sign which does not comply with Rule 605.e.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800649

Inspection Photos
Location Name: Blue Sky-69N91W /1SESE
Location ID: 313092




Photo 5. Photo taken in the interim area at the east of the Location shows Scotch thistle (List B Noxious). Note also good establishment of perennial grasses.



Photo 6. . Photo taken in the interim area at the north of the Location shows Canada thistle (List B Noxious).

Inspection Photos
Location Name: Blue Sky-69N91W /1SESE
Location ID: 313092



Photo 7. Photo taken at the northern edge of the working pad area shows diffuse knapweed (List B Noxious).



Photo 8. Photo taken in the interim area at the north of the Location shows good establishment of perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800649