

Inspection Photos

Loc: 333870

Operator: SIMCOE LLC

Inspection Date: 8/30/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 333870 | Date: 8/30/2022

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333870 | Date: 8/30/2022

Inspection Photos



Photo 2. Facing northeast at the location. Stormwater had washed thru this area and displaced the wattles at the red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 333870 | Date: 8/30/2022

Inspection Photos



Photo 3. Facing southwest at the entrance of the location. Stormwater directed from the previous photo has washed gravel off the road onto the adjacent land.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Loc: 333870 | Date: 8/30/2022