

PETRO MEX RESOURCES – 10059
API# 05-077-08012 COAL GULCH #2
Inspection Date : 9/6/2022



Location overview looking N



Wellhead with Pump Jack, Separator and Produced water tank

PETRO MEX RESOURCES – 10059
API# 05-077-08012 COAL GULCH #2
Inspection Date : 9/6/2022



Meter housing with sign.