

Sunical 1

API 05-067-05436

Response to Field Insp 702500334 from Alex Klink/COGCC
dated 08/24/2022



ROBERT L BAYLESS
PRODUCER LLC

SIGNS/MARKERS: Tank near Bayless wellpad belongs to Red Willow's dehy. Not Bayless'.

GOOD HOUSEKEEPING:

- Removed unused chemical drum near wellhead.



- Compressor Building panels removed from ground.



Sunical 1

API 05-067-05436

Response to Field Insp 702500334 from Alex Klink/COGCC
dated 08/24/2022



ROBERT L BAYLESS
PRODUCER LLC

EQUIPMENT:

- Rig anchor marked



- 1" flowline locked out/tagged out

